



**1. SCOPE**

This document details the application of SOP 2007/0346/00 (Applicable to Statter VLTB and VLTC RMU's) issued by the Energy Networks Association.

**2. ISSUE RECORD**

This is a controlled maintained document.

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
June 2009	1	David Walker	

**3. ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
David Walker Senior Project Engineer	Alastair Ferguson Asset Risk Manager	Jim Sutherland Chief Engineer .....



---

**4. SOP DETAILS**

**EQUIPMENT TYPE:** Statter VLTB and VLTC RMU's

**ORIGINATING DNO** Western Power Distribution

**DATE:** 07/12/2007

**NUMBER INSTALLED IN ENERGY NETWORKS NORTH:** 0

**NUMBER INSTALLED IN ENERGY NETWORKS SOUTH:** 0

**REASON:** Broken roll pin found on final drive to intank contacts of RH ring-switch

**STATUS IN INITIATING DNO:** a/ Access to s/s restricted to essential operational purposes only.  
b/ No live operation of either ring switch.  
c/ Dead operation of either ring switch should be avoided.

SOP can be lifted when the drive pins to both ring switches have been changed.

**SPEN APPLICATION:** No units of this type on the SP T&D network. This SOP for information only.

**UPDATE:** N/A

**REMEDIAL ACTION:** None required.