



1 SCOPE

This document details the application of SOP 5 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Switchgear & Cowan RA04 Oil Switch (R.M.U.)

ORIGINATING REC: Eastern Electricity Board

DATE: 30/5/79

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb system).

REASON: Double locknut on centre phase assembly came loose on early unit without pinned castellated nut.

UPDATE:

REMEDIAL ACTION: Replace nut assembly on old type locknut.