



1 SCOPE

This document details the application of SOP 6 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Brush 350 MVA 11 kV Oil Switches, OL, ON, HF & NF.

ORIGINATING REC: Eastern Electricity Board

DATE: 13/8/79

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System).

REASON: Refitting of modified test stalks required accurate replacement to avoid loosening of clamping bolts. See SOP 1.

UPDATE:

REMEDIAL ACTION: Check test stalk mounting block bolts for tightness.