



1 SCOPE

This document details the application of SOP 17 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Long & Crawford ETV2 11 kV OFS Earth Switch

ORIGINATING REC: South Western Electricity Board

DATE: 18/5/81

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb system).

REASON: Design fault on modification to 3 second delay mechanism caused disruptive failure when closing earth switch onto live cable.

UPDATE:

REMEDIAL ACTION: Incoming cable must be dead before earthing. Modification required.