



1 SCOPE

This document details the application of SOP 20 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Switchgear & Cowan K1 33 kV O.C.B.

ORIGINATING REC: Eastern Electricity Board

DATE: 20/8/82

NO. INSTALLED IN MANWEB: 3
NO. INSTALLED IN SCOTLAND:

STATUS: RESTRICTION (All known units in Manweb replaced therefor no restriction in Manweb.)

REASON: Failed to clear fault current.

UPDATE:

REMEDIAL ACTION: Units replaced in 1987.