



1 SCOPE

This document details the application of SOP 24 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: South Wales Switchgear Tiger 11 kV r.m.u.

ORIGINATING REC: South Wales Electricity Board

DATE: 26/8/83

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Operational Ban (None on Manweb system)

REASON: Feeder oil switches on some units failed to open when operated due to defective bracket on operating mechanism.

UPDATE:

REMEDIAL ACTION: Modification required.