



1 SCOPE

This document details the application of SOP 25 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Long & Crawford J1, J2, R & R2 11 kV Oil Switches

ORIGINATING REC: East Midlands Electricity Board

DATE: 21/9/83

NO. INSTALLED IN MANWEB: 272 J, 136 RNETV2

NO. INSTALLED IN SCOTLAND

STATUS: Live operation banned until modified.

REASON: Moisture ingress through earth stud and lid gasket. This caused corrosion of operating mechanism, and stiffness in operation.

UPDATE:

REMEDIAL ACTION: Inspection and modification required. See P.S.B. No. 46.