



1 SCOPE

This document details the application of SOP 32 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy 11 kV FRMU Mk1

ORIGINATING REC: MANWEB

DATE: 22/5/85

NO. INSTALLED IN MANWEB: 230

NO. INSTALLED IN SCOTLAND:

STATUS: Live operation banned until modified.

REASON: Concentric tube breather allowed water ingress.

UPDATE:

REMEDIAL ACTION: Seal breather. See P.S.B. No. 12.