



1 SCOPE

This document details the application of SOP 36 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Reyrolle 145 kV SF6 SPL C.B.

ORIGINATING REC: CEGB

DATE: 17/12/85

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: None on Manweb System

REASON: Tests showed 'detent' device in pneumatic mechanism subject to stiction if not frequently operated.

UPDATE:

REMEDIAL ACTION: Procedure to confirm correct operation.