



## 1 SCOPE

This document details the application of SOP 48 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Switchgear & Cowan RA4 & RAE4 11 kV R.M.U.

**ORIGINATING REC:** MANWEB

**DATE:** 8/7/87

**NO. INSTALLED IN MANWEB:** 2900

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Live operational ban until handle modified.

**REASON:** Swan neck oil switch operating handles were defective.

**UPDATE:**

**REMEDIAL ACTION:** Stiffening brace on swan neck handle required. Defective handles to be replaced. See P.S.B. No. 28.