



1 SCOPE

This document details the application of SOP 59 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire TYKE 11 kV R.M.U. (NO. T1125-T2572)

ORIGINATING REC: SEB

DATE: 4/5/88

NO. INSTALLED IN MANWEB:9

NO. INSTALLED IN SCOTLAND:

STATUS: Live operational ban until inspected.

REASON: Pins which stopped rotation of fixed earthing contacts securing screws were omitted, leading to inadequate earth contact.

UPDATE:

REMEDIAL ACTION: Units in Manweb to be replaced.