



## 1 SCOPE

This document details the application of SOP 61 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Yorkshire FMS Mk1 11 kV Oil Switches

**ORIGINATING REC:** SSEB

**DATE:** 1/7/88

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None on Manweb System).

**REASON:** Deterioration of Permali supports. See SOP 49

**UPDATE:**

**REMEDIAL ACTION:** All units to be replaced. See SOP 49