



1 SCOPE

This document details the application of SOP 66 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Long & Crawford WPD Mk2 11 kV O.C.B.

ORIGINATING REC: SWEB

DATE: 27/10/88

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND

STATUS: Restriction (None on Manweb system).

REASON: Operating mechanism adjustment varied resulting in
o.c.b. slow opening when springs recharged with o.c.b. closed.

UPDATE:

REMEDIAL ACTION: Check adjustment carefully.