



## 1 SCOPE

This document details the application of SOP 70 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Lucy TRMU & TSU Mk1, 2 & 2AS Switchgear

**ORIGINATING REC:** SWaEB

**DATE:** 7/2/89

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None on Manweb System)

**REASON:** Moisture ingress through breather and test access drain holes, lead to failure.

**UPDATE:**

**REMEDIAL ACTION:** Modification required.