



1 SCOPE

This document details the application of SOP 72 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Switchgear & Cowan RAO4 & RAO50 11 kV
R.M.U.

ORIGINATING REC: NORWEB

DATE: 20/2/89

NO. INSTALLED IN MANWEB:0, but RA4 has similar mechanism

NO. INSTALLED IN SCOTLAND:

STATUS: Operation restricted until checked

REASON: Pin in operating mechanism may be loose or damaged.

UPDATE:

REMEDIAL ACTION: Inspection required. Instruction issued. See P.S.B. No. 19.