



1 SCOPE

This document details the application of SOP 80 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire AFS 14 & TYKE MK1 11 kV switchgear.

ORIGINATING REC: MEB

DATE: 5/5/89

NO. INSTALLED IN MANWEB:9
NO. INSTALLED IN SCOTLAND:

STATUS: Live operation banned until inspection.

REASON: Mechanical defect on o.c.b. contacts prevented full closure of contacts.

UPDATE:

REMEDIAL ACTION: Inspection required. Replace units in Manweb.