



1 SCOPE

This document details the application of SOP 85 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy FRMU

ORIGINATING REC: Northern Ireland Electricity

DATE: 13/10/89

NO. INSTALLED IN MANWEB: 500

NO. INSTALLED IN SCOTLAND:

STATUS: Operational restriction until inspected.

REASON: Operation with 'Move Earth' Selector in wrong position became dependant manual in operation.

UPDATE:

REMEDIAL ACTION: Ensure interlock selector is in correct position for operation.
See P.S.B. No. 12 and 47.