



1 SCOPE

This document details the application of SOP 90 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: LONG & CRAWFORD J3, J3X, J4, J4X, R3, R4, T3GF3 and T4GF3 11 kV R.M.U. Manweb affected.

ORIGINATING REC: SWEB

DATE: 10/11/89

NO. INSTALLED IN MANWEB:(pre 1981) 501

NO. INSTALLED IN SCOTLAND:

STATUS: Operation restricted until inspected.

REASON: Brass bolts fitted to secure test access covers on pre-1981 units sheared allowing water ingress.

UPDATE:

REMEDIAL ACTION: Steel bolts to be fitted to all units, to replace brass bolts, or where bolts are intact, a sta-strap cable tie fitted. See PSB 53.