



1 SCOPE

This document details the application of SOP 91 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy TRMU & TSU Mk1, 2, 3 & 2AS 11 kV
R.M.U.

ORIGINATING REC: SWALEC

DATE: 17/1189

NO. INSTALLED IN MANWEB:0
NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System)

REASON: Main oil switch blade became detached from its cable
spill, resulting in open circuit.

UPDATE:

REMEDIAL ACTION: Inspection required.