



1 SCOPE

This document details the application of SOP 93 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

| Issue Date | Issue No | Author | Amendment Details |
|--------------|----------|----------------|---|
| October 2000 | 1 | Esther Stewart | Initial Issue in New Format: 2 Page Document |

3 ISSUE AUTHORITY

| Author | Owner | Issue Authority |
|----------------|--------------|--|
| Esther Stewart | Roger Bracey | Roger Bracey Group Head, Standards |



4 SOP DETAILS

TYPE: STATTER TYPE OFS, VL Mk1 & 2, VL/2 -
ODSA & VLE Mk2. 11kV Switchgear

ORIGINATING REC: SWEB

DATE: 2/2/90

NO. INSTALLED IN MANWEB: 14

NO. INSTALLED IN SCOTLAND:

STATUS: Live operation banned

REASON: Moisture ingress caused tank explosion when closing
onto l.v. fault.

UPDATE:

REMEDIAL ACTION: All units to be replaced.