



1 SCOPE

This document details the application of SOP 94 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC DD O.C.B.'s

ORIGINATING REC: MEB

DATE: 18/2/90

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System)

REASON: Mechanism defect could allow slow closure without spring assistance.

UPDATE:

REMEDIAL ACTION: Defect from 1967, not adequately modified on this o.c.b.