



1 SCOPE

This document details the application of SOP 95 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Whipp & Bourne CV 11/6.6 kV C.B. 1250A and 2000A Units)

ORIGINATING REC: NORWEB

DATE: 13/3/90

NO. INSTALLED IN MANWEB:2

NO. INSTALLED IN SCOTLAND:

STATUS: Live Operation banned until modified.

REASON: Distortion of busbar segregation access interlock bar preventing operation of BB isolator from Off to Circuit earth.

UPDATE:

REMEDIAL ACTION: Inspection and modification required. Instruction issued.