



1 SCOPE

This document details the application of SOP 98 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Long & Crawford J Oil Switch

ORIGINATING REC: SEB

DATE: 25/5/90

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND

STATUS: Ban (None on Manweb System)

REASON: Earth barrier in switch tank contacted centre phase BB as test prods were inserted.

UPDATE:

REMEDIAL ACTION: Insertion of test prods, for serial Nos. prefix 63 and lower, banned until checked. Restriction now removed.