



## 1 SCOPE

This document details the application of SOP 104 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

| Issue Date   | Issue No | Author         | Amendment Details                               |
|--------------|----------|----------------|---|
| October 2000 | 1        | Esther Stewart | Initial Issue in New Format:<br>2 Page Document |

## 3 ISSUE AUTHORITY

| Author         | Owner        | Issue Authority                                |
|----------------|--------------|--|
| Esther Stewart | Roger Bracey | Roger Bracey<br>Group Head, Standards<br>..... |



#### **4 SOP DETAILS**

**TYPE:** NEI REYROLLE YMV2

**ORIGINATING REC:** Northern Electric

**DATE:** 18/12/90

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Live Operation banned (None on Manweb System). .

**REASON:** Disruptive failure of 11kV VCB.

**UPDATE:**

**REMEDIAL ACTION:** Modification required. Operate remotely. Access restricted.