



## 1 SCOPE

This document details the application of SOP 110 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### **4 SOP DETAILS**

**TYPE:** Brush 11kV VBA R4/1 and 8/1

**ORIGINATING REC:** SWEB

**DATE:** 8/7/91

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Access restricted. (None in Manweb)

**REASON:** Spout failures after lightning.

**UPDATE:** 2/8/94: SOP withdrawn.

**REMEDIAL ACTION:** Minimise access to substations containing live VBA equipment and vacated during lightning.