



## 1 SCOPE

This document details the application of SOP 132 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** ACS Transtech - Hook Stick Air Break Isolator  
Distrolec.

**ORIGINATING REC:** MEB

**DATE:** 19/1/94

**NO. INSTALLED IN MANWEB:** 0  
**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None in Manweb).

**REASON:** Faulty operating arm on the 11kV 400Amp hook stick air break  
isolator. This SOP applies only to those isolator units supplied  
between June 1993 until December 1993.

**UPDATE:**

**REMEDIAL ACTION:** Dead operation only until the unit has been modified.