



1 SCOPE

This document details the application of SOP 137 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy MkII TRMU & TSU 11kV 250MVA oil filled RMU

ORIGINATING REC: SWALEC

DATE: 5/9/94

NO. INSTALLED IN MANWEB: 0
NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb system)

REASON: Disruptive failure during switching one unit.

UPDATE:

REMEDIAL ACTION: None.