



1 SCOPE

This document details the application of SOP 144 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: ATL type ASD and AMD 132/33kV
Transformer tap-changers

ORIGINATING REC: East Midlands & Seeboard

DATE: 7/4/95 & 11/4/95

NO. INSTALLED IN MANWEB: 3 (ASD only in Manweb)
NO. INSTALLED IN SCOTLAND:

STATUS: Restriction

REASON: Disruptive failure of unit reported by Manweb and Seeboard.

UPDATE:

REMEDIAL ACTION: Work in the vicinity of the transformer is prohibited for all but essential work.