



1 SCOPE

This document details the application of SOP 146 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: B & S Fuse, 11kV D.O.E.F. Type Delta
2.

ORIGINATING REC: Scottish Hydro-Electric

DATE: 25/5/95

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None in Manweb)

REASON: Failure of steelwork mounting bracket.

UPDATE:

REMEDIAL ACTION: Ban on live and dead operation of fuse units imposed when new brackets were fitted.