



1 SCOPE

This document details the application of SOP 151 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: ABB Nitran shrouded LV fuse cabinets and pillars with test sockets

ORIGINATING REC: MEB

DATE: 17/8/95

NO. INSTALLED IN MANWEB: 2
NO. INSTALLED IN SCOTLAND:

STATUS: No Restriction in Manweb

REASON: A three phase flashover occurred on a ABB Nitran lv cabinet in Midlands Electricity whilst a jointer was testing phase rotation upon commissioning, via the test socket on the cabinet

UPDATE:

REMEDIAL ACTION: Test sockets on all ABB shrouded fusegear are not to be used. It is not current Manweb practice to utilise a test socket on such fusegear.