

# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-154 **SOP 154**

Issue No. 1 October 2000

#### **SCOPE** 1

This document details the application of SOP 154 issued by the Electricity Association.

### 2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

### **ISSUE AUTHORITY**

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-154 **SOP 154**

Issue No. 1 October 2000

4	SOP	<b>DETAILS</b>
---	-----	----------------

**TYPE:** S&C K3 OCB UNITS (33kv)

**ORIGINATING REC: NORWEB** 

11/10/95 **DATE:** 

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

**STATUS:** Ban (None in MANWEB)

Access to switchroom containing live K3 equipment restricted to that required for essential operational purposes. Live operation to be carried out by remote control only, no personnel to be in switchroom at the time. No protracted work to be carried out in a switchroom unless all the K3 type switchgear within the room is made dead.

**REASON:** 

Disintegration of bushing insulation found during maintenance.

**UPDATE:** 

**REMEDIAL ACTION:**