



1 SCOPE

This document details the application of SOP 156 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: REYROLLE JKSS 11kV RMU
ORIGINATING REC: NORTHERN IRELAND ELECTRICITY
DATE: 18/12/95
NO. INSTALLED IN MANWEB: 45
NO. INSTALLED IN SCOTLAND:

STATUS: Restriction:

Tee off/transformer switch must not be operated into the earth position with the unit live.

REASON:

Failure of fixed earthing contact associated with the tee off/transformer switch.

UPDATE:

REMEDIAL ACTION:

To earth tee off the unit must be isolated and the integrity of the fixed earthing contact verified by internal inspection. Within MANWEB all units to be replaced as part of refurbishment plan.