



1 SCOPE

This document details the application of SOP 160 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: SWS IF4X

ORIGINATING REC: NORWEB

DATE: 29/02/96

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban on live operation of ring switches (None in MANWEB).

REASON: Selector mechanism disengaged resulting in the earthing of a live feeder.

UPDATE:

REMEDIAL ACTION: Investigations ongoing