



1 SCOPE

This document details the application of SOP 166 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC TYPE KNB 11KV OCB

ORIGINATING REC: MIDLANDS ELECTRICITY

DATE: 02/07/96

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: None in MANWEB. No operation with staff in switchroom.

REASON: Disruptive failure of ocb resulting in major structural damage to substation.

UPDATE:

REMEDIAL ACTION: Still under investigation