



1 SCOPE

This document details the application of SOP 168 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Reyrolle Type ROK SS 11kV rmu
(1990 onwards)

ORIGINATING REC: East Midlands

DATE: 22/08/96

NO. INSTALLED IN MANWEB: 0
NO. INSTALLED IN SCOTLAND:

STATUS: All restrictions under this SOP withdrawn

REASON: Contaminated oil caused oil switch to seize

UPDATE:

13/09/96 Investigations have failed to determine the cause of the original problem and sampling of other units has revealed no similar problems. All restrictions notified under SOP 168 are withdrawn. Having taken account of all relevant factors it is considered most unlikely that this incident will be repeated.

REMEDIAL ACTION: