



1 SCOPE

This document details the application of SOP 180 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Morris Line Equipment Ltd. Type RL 33kV Air Break Switch

ORIGINATING REC: NORTHERN ELECTRIC

DATE: 21/04/97

NO. INSTALLED IN MANWEB: 0
NO. INSTALLED IN SCOTLAND:

STATUS: Ban on Live Operation.

REASON: Flashover of 33kV load break switch with interrupter heads during operation to de-energise cable.

UPDATE:

REMEDIAL ACTION:.