



## 1 SCOPE

This document details the application of SOP 183 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** All Oil Switches, RMU's & Switchfuses.

**ORIGINATING REC:** East Midlands Electric

**DATE:** 22/05/97

**NO. INSTALLED IN MANWEB:**

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** BAN (No Restriction to be applied In MANWEB)

**REASON:**

A number of mal-operations of oil filled units commissioned or maintained from January 1989 to December 1991.

This is an oil sludging problem associated with a particular manufacturer (not used by MANWEB), no similar problems have been experienced in Manweb and Manweb's current maintenance and oil handling procedures are considered to be sufficient to avoid problems.

See Scottish Power Operational Restriction 49.

**UPDATE:**

**REMEDIAL ACTION:**