



1 SCOPE

This document details the application of SOP 185 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC/English Electric Type T3OF 11kV RMU

ORIGINATING REC: Northern Ireland Electric

DATE: 27/06/97

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban on Live Operation (None on Manweb system).

No live operation and No switching operations to be carried out even with the unit isolated.

REASON:

Internal shrouding of unit had broken away and fallen across the left ring switch, which obstructed the moving blade assembly from making contact with the fixed earth contacts when being switched on. The indication on the unit showed the earth to be in the ON position.

UPDATE:

REMEDIAL ACTION:

All units to be inspected and remedial action taken as necessary. Details of action to be taken still being discussed with the manufacturer and will be issued when agreed.