



## 1 SCOPE

This document details the application of SOP 194 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

| Issue Date   | Issue No | Author         | Amendment Details                               |
|--------------|----------|----------------|---|
| October 2000 | 1        | Esther Stewart | Initial Issue in New Format:<br>2 Page Document |

## 3 ISSUE AUTHORITY

| Author         | Owner        | Issue Authority                                |
|----------------|--------------|--|
| Esther Stewart | Roger Bracey | Roger Bracey<br>Group Head, Standards<br>..... |



#### 4 SOP DETAILS

**TYPE:** Long & Crawford T3GF3 and GF3  
(T3GF3 - 747631, T4GF3 - 747646)  
This equates to late 1974 production.

**ORIGINATING REC:** Northern Ireland Electricity.

**DATE:** 11/10/97

**NO. INSTALLED IN MANWEB:** 195  
**NO. INSTALLED IN SCOTLAND**

**STATUS:** Ban (No Restriction applied In Manweb).

**REASON:**

Broken fuse contact clips and loose retaining pins found during maintenance.

**UPDATE:**

**REMEDIAL ACTION:**

Clips to be inspected during maintenance and replaced if necessary.

After the first cracked clip was found, L & C undertook tests to prove that the unit will carry FULL LOAD current with clips suffering various types of crack. Therefore the decision to change only when found broken.