



1 SCOPE

This document details the application of SOP 199 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Merlin Gerin YSF6 11,000/110V VT

ORIGINATING REC: East Midlands Electric

DATE: 11/10/97

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban on Live Operation. (Units not to be withdrawn/replaced live)

REASON:

A number of failures in service in East Midlands Electric and other companies.

UPDATE:

REMEDIAL ACTION:

The manufacturer of the affected voltage transformers (Merlin Gerin) are carrying out a detailed investigation in conjunction with several UK REC's to establish the cause of the failures and to provide recommendations on what remedial action is to be taken.