



1 SCOPE

This document details the application of SOP 203 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Brush Current Transformer Type OH
145

ORIGINATING REC: Seeboard

DATE: 11/10/97

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS:

Restriction on access to compound at Kemsley only.

REASON:

Following the disruptive failure of a CT at Kemsley 132kV compound all the damaged insulators have been replaced as necessary. Loss angle tests on other CT's at the site are giving cause for concern. Further tests are to be carried out by Seeboard and NGC.

UPDATE:

REMEDIAL ACTION: