



## 1 SCOPE

This document details the application of SOP 209 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Reyrolle Type JK 11kV extensible oil fuse switch

**ORIGINATING REC:** SCOTTISHPOWER

**DATE:** 13/08/98

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** RESTRICTION.

No attempt shall be made to open the fuse compartment lid whilst any part of the equipment is live.

**REASON:**

Following an investigation into a ScottishPower defect report on a Reyrolle type JK 11kV oil fuse switch, it has been found that there is a risk of debris falling into the fuse compartment on outdoor switches. This restriction does not apply to indoor oil fuse switches.

**UPDATE:**

**REMEDIAL ACTION:**

All Reyrolle type JK 11kV oil fuse switches shall be replaced to programme.