



1 SCOPE

This document details the application of SOP 245 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Ferguson Palin Type BVRP 6.6/11kV OCB

ORIGINATING REC: Norweb

DATE: 26/11/99

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction.

OCB's of this type to have the springs charged in the isolated position only.

REASON:

OCB slow opened whilst engineer recharging springs immediately after closing the OCB in the service position.

UPDATE:

REMEDIAL ACTION: