



## 1 SCOPE

This document details the application of SOP 249 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### **4 SOP DETAILS**

**TYPE:** SWS 16 FRMU 11kV ring main unit

**ORIGINATING REC:** Hyder (Swalec)

**DATE:** 17/02/2000

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Restriction: The following operational restriction imposed by Hyder.

Serial number of equipment type 94341, Year of manufacture 1974. Ring switch operations only permitted with the unit "DEAD"

**REASON:**

Failure of indicator linkage and loose detached pin falling to bottom of tank.

**UPDATE:**

**REMEDIAL ACTION:**