

SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-250 **SOP 250**

Issue No. 1 October 2000

1 **SCOPE**

This document details the application of SOP 250 issued by the Electricity Association.

2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

ISSUE AUTHORITY 3

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-250 **SOP 250**

Issue No. 1 October 2000

SOP DETAILS

TYPE: Reyrolle C Type 11kV OCB

ORIGINATING REC: Midlands Electric

DATE: 17/03/2000

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

Restriction (No equipment of this type remaining in Manweb) **STATUS:**

The following restriction imposed by Midlands Electric: Springs to be charged only with the OCB in the isolated position.

REASON:

OCB started to slow close when springs were being recharged.

UPDATE:

REMEDIAL ACTION: