



## 1 SCOPE

This document details the application of SOP 251 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### **4 SOP DETAILS**

**TYPE:** Henley & Rchem 11kV Insulators/Surge Arresters.

**ORIGINATING REC:** Northern Ireland Electric

**DATE:** 27/03/00

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:**

No live line working to be carried out where low level tapping brackets are fitted or where a brass bail is fitted to a polymeric insulator.

**REASON:**

An insulator fitted to a tapping bracket fractured at the attachment stud (solid core) allowing the live conductor to swing free. This fracture could have occurred due to previous work carried out using live line techniques.

**UPDATE:**

**REMEDIAL ACTION:**