



1 SCOPE

This document details the application of SOP 265 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Lucy SCRMU

ORIGINATING REC : NIE

DATE : 26/10/2000

NO. INSTALLED IN MANWEB: None

STATUS : Restriction: Prove correct trip and close operation before energising.

REASON: During commissioning, the mechanism of a new SCRMU would not reset after tripping. Trip assist spring found dislodged.

UPDATE:

REMEDIAL ACTION: Faulty units to be inspected and repaired by Lucy Switchgear.