



## **1 SCOPE**

This document details the application of SOP 266 issued by the Electricity Association.

## **2 ISSUE RECORD**

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
August 2002	1	David Naylor	Initial Issue 2 Page Document

## **3 ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager  .....



**4 SOP DETAILS**

**TYPE :** Hawker Siddeley VMW circuit Breaker

**ORIGINATING REC :** State of Guernsey Electricity Board

**DATE :** 21/10/2000

**NO. INSTALLED IN MANWEB:** None

**STATUS :** Restriction: If circuit breaker fails to close electrically, breaker must be made dead before removal from housing.

**REASON:** See DIN 2000/0150/01. VCB failed to close on synchronising.

**UPDATE:**

**REMEDIAL ACTION:** Contact Dave Johnson at FKI Tel. 01495 331177.