



1 SCOPE

This document details the application of SOP 268 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Siemens type 8DA10 circuit breakers

ORIGINATING REC : PowerGen (East Midlands)

DATE : 01/12/99

NO. INSTALLED IN MANWEB: 225

STATUS : Restriction: **NO RESTRICTION IN MANWEB.**

REASON: PowerGen banned the use of circuit test arrangement due to lack of interlocks. Manweb units have additional Primary Earth indicator lamps, padlocking and key exchange procedure. Additional interlocking options under consideration.

UPDATE:

REMEDIAL ACTION: None required.