



1 SCOPE

This document details the application of SOP 273 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Yorkshire switchgear Tyke RMU

ORIGINATING REC : ScottishPower

DATE : 16/05/01

NO. INSTALLED IN MANWEB: 6

STATUS : Live operation and close access already banned in Manweb area under SOP49

REASON: Permali cross member that drives contacts of switchfuse deteriorated due to moisture ingress. Further failure incident.

UPDATE:

REMEDIAL ACTION: All units in Manweb area to be replaced.